




## Survey Instructions

### Measurements:

**Note:** *Measure the glass size only.*

- Measure the visible glass width at 3 different points as shown.  
**Use the smallest measurement as the blind width.**
- Measure the drop  
(ensure sizes are within specification as per table below)



Tensioned Bead Fit/Guided Bead Fit			
Max Width	1000mm	Min Width	250mm
Max Drop	2400mm	Min Drop	250mm
Max Area	2m <sup>2</sup>	Min Bead Depth	N/A

- Check the frame & rubber seal type  
(see diagram below)

**Square Frame with flush  
rubber seal  
Yes or No?**

